Section V - Reactivity Data		IDENTITY CERASOLZER ECO 155			
Stability	Unstable		Conditions to Avoid Keep away from heat, sparks and open flames.		
	Stable	x	Neep away irom	neep away from neat, sparks and open flames.	
Incompatibility Strong oxidizing materials, acids, hydrogen peroxide.					
Hazardous Decomposition or Byproducts NA					
Hazardous Polymerization	May Occur		Conditions to Av	roid NA	
	Will Not Occur	X			
Section VI — Health Hazard Data					
Route of Entry: Inhalation Skin			Skin	Ingestion	
Health Hazards When heated, vapors can cause irritation to eyes, nose and throat. May cause headache.					
Carcinogenicity: Not listed NTP			IARC Monograp	hs OHSA Regulated	
Signs and Symptoms of Exposure Symptoms of the neurological effects may include irritability, headaches, insomnia, delirium, convulsion, muscular tremors, and palsy of the extremities.					
Medical Conditions Generally Aggravated by Exposure					
Emergency and First Aid Pro Inhalation : Excessive over present, the in	exposure may result	in emov	an acute or chron ed from exposure	nic illness. If symptoms are and a physician consulted.	
Ingestion : Call a physician at once.					
Skin: For hot metal burns, exposed area shoud be cooled with water and get medical attention. After handling solder, wash throughly with soap and water.					
Section VII — Precautions for Safe Handling and Use					
Steps to Be Taken in Case Material is Released or Spilled Avoid inhalation of solder fume or dust. Vacuuming is recommended.					
Waste Disposal Method Contact supplier or a licensed chemical waste disposal contractor for treatment, packaging, and disposal requirements.					
Precautions to Be Taken in Handling and Storing Avoid breathing smoke during soldering. Wash hands before eating or smoking after handing solder					
Other Precautions					
Section VII — Control Measures					
Respiratory Protection A NIOSH approved dust/fum	e respirator should	be	worn where applic	cable limits may be exceeded.	
Ventilation Local Exhaust Remove smoke from breathing area			breathing area	Special Not required	
Mechanical				Other	
Protective Gloves Use plastic or rubber gloves and aprons where necessary to avoid skin contact. Eye Protection Safety glasses or goggles should be worn in areas where splashing may occur.					
Other Protective Clothing or Equipment Provide sufficient mechanical (general and/or local exhaust) ventilation to maintain exposure below TLV's.					
Work/Hygienic Practices					